



- ▲ boundary corner marker
 - manhole
 - spot point
 - best pit
 - boring
 - monitoring well
 - ▲ auger hole
- 1"=20'

Notes - small trees and shrubs cut by machine recently - noted by S. J. in field

Survey P.L. #11

Survey P.L. #12

Survey P.L. #13

Survey P.L. #14

Survey P.L. #15